

Instructions for use of PT-2000 PORTA-MATIC

READ CAREFULLY BEFORE USING THIS MACHINE

The "PT-2000" PORTA-MATIC can be used to salvage a cylinder block which has a damaged or cracked counterbore ledge. The original block liner counterbore ledge is machined out and a repair bushing which forms a new counterbore is installed. The bores can be enlarged and a new bushing installed in about five minutes per bore. This time does not include checking and finish machining the counterbore ledge. Finish cutting the counterbore ledge after rebushing takes about three to five minutes a bore, with the "PT-2000" Counterbore Tool.

The counterbore repair bushings, part nos. PT-8000 (V12 NH 5½ IN bore), PT-8060 (NH 5-1/8 IN bore) and PT-8070 (V-903), are available from KENT-MOORE TOOL DIV. When installed, the bushing counterbore ledge must be cut deeper to meet Cummins Specifications.




Fig. 1 Repair Bushing




Fig. 2 Breakdown of parts.



Kent-Moore
TOOL DIVISION

P.O. BOX 647 ■ 827 JEFFERSON AVE.
CLOVIS, CALIFORNIA 93613
Telephone: 209/299-4351



PARTS BREAKDOWN FOR "PT-2000" PORTA MATIC:

Det. #	Part #	Part Description	Amt.	Det #	Part #	Part Description	Amt.
1	PT-2000-001	Main Housing Assy.	1	22	PT-2000-015	Base Plate	1
2	PT-2000-040	Drive Bracket (NS)	1	23	PT-2000-016	1" Stud Adapters	4
3	PT-2000-003	Drive Shaft (NS)	1	24	PT-10097	Soc. Hd. Cap Scr. (NS)	2
4	PT-2000-004	Drive Sprocket (NS)	1	25	PT-11010	Nut (NS)	2
5	PT-2000-056	Drive Chain (NS)	1	26	PT-11012	Jam Nut	2
6	PT-16039	Spline Sprocket	1	27	PT-2000-017	Cutoff Washer	1
7	PT-2000-005	Spline Washer (NS)	1	28	PT-10095	Soc. Hd. Cap Scr. (NS)	4
8	PT-2000-047	Depth Set Collar	1	29	PT-2000-018	Driver Plate	1
9	PT-2000-007	Needle Valve Knob	1	30	PT-2000-019	Driver Handle	1
10	PT-2000-050	Cutter Plate (5-1/8 Bore)	1	31	PT-2000-051	Cutter Plate (5½ Bore)	1
11	PT-2000-009	Cutter Holder Plate (NS)	1	32	PT-2000-021	¾" Stud Adapter	4
12	PT-10002	Soc. Hd. Cap Scr. (NS)	2	33	PT-12008	Washer (7/8 S.A.E.)	5
13	PT-2000-045	Cutter	2	34	PT-2000-023	Guide Plate (5-1/8 Bore)	1
14	PT-10112	Swivel Pad Set Scr. (NS)	1	35	PT-2000-022	Guide Plate (5½ Bore)	1
15	PT-2000-011	Cutter Adj. Pin. (NS)	1	36	PT-2000-024	Guide Plate (V-903)	1
16	PT-16081	Cutter Adj. Spring (NS)	1	37	PT-2000-025	Bushing Driver Shaft (long)	1
17	PT-2000-079	Soc. Set Scr. (NS)	1	38	PT-2000-026	Bushing Driver Shaft (short)	1
18	PT-2000-039	Micrometer Block	1	39	PT-1000-020	Universal Drive (NS)	1
19	PT-2000-013	Micrometer (NS)	1	40	PT-2000-029	Setting Standard (NS)	1
20	PT-10002	Soc. Hd. Cap Scr. (NS)	2	41	PT-12014	Washer (¾ STD.)	4
21	PT-2000-014	Cutter Stop (NS)	1	42	PT-10002	Soc. Hd. Cap Scr. (NS)	1

*Denotes items not shown in breakdown picture.

THE MICROMETER BLOCK

The MICROMETER BLOCK is preset at the factory with a direct reading micrometer (19); the reading on the micrometer directly corresponds to the bore size to be cut. However, due to shipping the MIKE BLOCK may be out-of-adjustment.





Fig. 3 Micrometer Block with Cutter

CHECKING THE MIKE BLOCK

1. Using the SETTING STANDARD (40) to check the micrometer reading, place the setting standard with side stamped "UP" on top between the cutter stop (21) and the micrometer spindle. Turning the thimble move the spindle snugly against the setting standard (40). Micrometer reading should be 5.000. See Dwg. #1.



Dwg. 1 Adjusting Micrometer



Kent-Moore
TOOL DIVISION

P.O. BOX 647 ■ 827 JEFFERSON AVE.
CLOVIS, CALIFORNIA 93613
Telephone: 209/299-4351



PORTA-TOOL
PRODUCTS

If adjustment is necessary loosen socket head set screw (20) and set micrometer (19) at 5.000.

3. Slide micrometer (19) snugly against setting standard (40) and tighten socket head set screw (20).

4. As a further check, back-off thimble on micrometer (19) and recheck reading.

SETTING THE CUTTER

1. Loosen socket set screw (17) in back-end of cutter (13) and push spring-loaded adjusting pin (15) all-the-way in. Tighten socket set screw (17).

2. Using the Micrometer Block (18) set the micrometer to the following sizes depending on the block you are to bore:

V12, 5-1/2 NH bore	6.750 dia.
V-903	6.625 dia.
V12, 5-1/8 NH bore	6.275 dia.

NOTE: Final cut inside diameter must be within plus or minus .001 of above dimensions.

3. Place cutter (13) in MIKE Block (18) as shown in Dwg. 1 firmly against cutter stop (21).

4. Loosen cutter socket set screw (17) and allow adjusting pin (15) to snap out against micrometer spindle. Lock socket set screw (17).

5. As a further check, back-off thimble on micrometer and recheck cutter length again. Back off on micrometer to remove cutter.

PREPARING THE BLOCK

1. Steam clean the block and remove all top deck dowels.

2. Remove all burrs and high spots from top deck with a large mill file. Finish dress with a flat stone.

3. Remove all dents or burrs from the counterbore inside diameter to be cleaned with an emery cloth. This area is used to locate the tool.

ASSEMBLING THE TOOL

1. Select the correct cutter plate (10 or 31) to be used.

2. Assemble cutter plate (10 or 31) on shaft of the main housing (1) and secure with nut (26) and washer (27). See Fig. 4.




Fig. 4 Attaching the Cutter Plate

MACHINING THE BLOCK

1. Making sure the cutter (13) is removed from the cutter plate (10 or 31), place the boring machine on the cylinder block above the bore to be cut and start mounting the head cap screws, leave loose. The stud adapter (23 or 32) must be on the cap screws.




Fig. 5 Preparing to Install Cutter



Kent-Moore
TOOL DIVISION

P.O. BOX 647 ■ 827 JEFFERSON AVE.
CLOVIS, CALIFORNIA 93613
Telephone: 209/299-4351



PORTA-TOOL
PRODUCTS

2. Lower the cutter plate (10 or 31) into the bore by turning the valve knob (9) counter-clockwise while pushing down.

3. The cutter plate lower diameter is used to center the boring machine in the counterbore. Push cutter plate lower locating diameter into the counterbore and now tighten the four head cap screws alternately to 50 ft. lbs. torque. (See Fig. 6).





Fig. 6 Mounting Porta-Matic on Block

4. Retract cutter plate (10 or 31) by pulling up on the needle valve knob (9). Once the cutter plate (10 or 31) is at its highest position lock in place by turning the valve knob (9) clockwise till snug.

5. Insert cutter (13) into cutter plate (10 or 31) and tighten cutter plate swivel pad set screw (14). The cutter (13) must be held all the way in against the main shaft of the boring tool.

NOTE: The sharp tip of the cutter must be inserted into the slot in the cutter holder with the tip of the lower left side of the slot. (See Dwg. 2)

NOTE: The cutters have a shallow hole in them. This must face downward when the cutter is inserted in the slot.



Dwg. 2 Inserting Cutter

6. Place the 0.004 inch feeler gauge between block and the cutter (13). Lower the cutter (13) the feeler gauge by turning the needle valve knob while pushing down very gently. (See Fig. 7).




Fig. 7 Use of Feeler Gauge to Set Depth of Cut

7. Loosen the socket cap screw (42) on the depth set collar and back-off the depth set collar (8) counterclockwise. Place the bushing to be used between the depth set collar and the sprocket and adjust depth set collar down to bushing, tighten socket cap screw. (See Fig. 8).

This spaces the depth set collar (8) to cut to a depth 0.004 inch less than the total height of the salvage bushing to be used.




Fig. 8 Setting Length of Cut

8. Remove the feeler gauge from below cutter (13) and pull up on needle valve knob to return cutter to top position. Turn needle valve knob clockwise to close valve to hold it in "UP" position.

9. Chuck the 1/2 inch universal drive adapter (39) in a 1/2 to 3/4 inch heavy duty (10 amp. or more) hand drill.



Kent-More
TOOL DIVISION

P.O. BOX 647 ■ 827 JEFFERSON AVE.
CLOVIS, CALIFORNIA 93613
Telephone: 209/299-4351



PORTA-TOOL
PRODUCTS

10. With the hand drill on the universal drive adapter (30) commence boring until the machine freewheels (approx. 2 minutes). About half-way down during the cut the cutter begins cutting out the old counterbore ledge. The operator should have a firm grip on the hand drill to be prepared for the increased load on the hand drill from the added metal being cut. Stop immediately when the cutter freewheels or some chatter may occur. (See Fig. 9).




Fig. 9 Starting the Bore Cut

11. Retract the cutter plate (10 or 31) by turning the needle valve knob counter-clockwise and pulling up. Turn needle valve knob clockwise to close valve to hold it in the up position. Remove the cutter (13) from the cutter plate and then remove the boring machine. (See Fig. 10).




Fig. 10 Retracting Cutter Plate

12. Clean away all shavings and deburr the bore with emery cloth.

13. Clean the cutter recess in the cutter plate (10 or 31) and remove all chips and material. Also there is an access area where the cutter contacts the main shaft; it is easy to clean this area with a "Q" Tip so you don't bore oversize by accident. However, we do stock oversized repair bushings — just in case you should ever overbore. All we need to know is exactly what size hole you've bored. We can then send you a bushing to fit your bore.

14. IMPORTANT! It is imperative that you bore your hole and install the repair bushing before going on to the next hole. Never bore all the cylinder bores and then expect to install the repair bushings.

15. If the block is to be resurfaced, the rebushing operation should be done first — and at least four hours should elapse before resurfacing the block; this gives the Loctite time to set up.

16. Rebushing the counterbore is a very successful operation if the job is done correctly; over 50,000 blocks have been saved in this manner since 1967.

INSTALLING THE SALVAGE BUSHING

1. Clean the bore and bushing outside diameter thoroughly with PT-7270 PRIMER-T. (See Fig. 11).




Fig. 11 Cleaning Bore with Primer-T

2. Coat the outside diameter of the bushing lightly with PT-7260 LOCTITE COMPOUND and drive it into the bore with the bushing driver (29) using a soft hammer until it bottoms. A solid sound can be heard when the bushing bottoms. (See Fig. 12). Also see Fig. 14 on back side (this page) which shows bushing driver assembled.




Fig. 12 Driving the bushing into the bore.



Kent-Moore
TOOL DIVISION

P.O. BOX 647 ■ 827 JEFFERSON AVE.
CLOVIS, CALIFORNIA 93613
Telephone: 209/299-4351



PORTA-TOOL
PRODUCTS

3. The bushing will protrude above the top of the block approximately 0.004 inch and must be filed even with the top deck. Remove all burrs with emery cloth. (See Fig. 13).



Fig. 13 Finishing The Block

4. Check counterbore depth and cut to depth per normal procedures. The salvage bushing is designed to be 0.005 to 0.010 inch shallow of required counterbore depth. This means it must be cut 0.005 to 0.351 in on NH 5½ inch bore). Refer to "SHOP MANUALS" to get correct depth of counterbore for other engine models. Use the "PT-2200" COUNTERBORE TOOL for this operation.




Fig. 14 Assembled Bushing Driver

CARE OF HYDRAULIC FEED HOUSING: A periodic check should be made to see if the main housing is completely full of 30 W Non-detergent oil. If low on oil the tool will chatter. To check oil level turn the valve knob counterclockwise and press the tool down to it's lowest position then add oil if necessary.

PT-7270 PRIMER-T and PT-7260 LOCTITE COMPOUND
are available from:

**KENT-MOORE
TOOL DIVISION
P. O. Box 647
827 Jefferson Avenue
Clovis, CA. 93613 (209) 299-4351**

